

Size		1/32	3/64	1/16	(5/64)	3/32	7/64	1/8	9/64	5/32
A	max	0.034	0.050	0.063	0.079	0.093	0.107	0.124	0.138	0.154
	min	0.028	0.044	0.056	0.072	0.086	0.100	0.116	0.130	0.146
B	max	0.032	0.048	0.060	0.076	0.090	0.104	0.120	0.134	0.150
	min	0.022	0.035	0.044	0.057	0.069	0.080	0.093	0.104	0.116
c	min	0.060	0.090	0.120	0.160	0.190	0.220	0.250	0.280	0.310
D	min	0.010	0.020	0.030	0.040	0.040	0.050	0.060	0.060	0.070

Size		3/16	(7/32)	1/4	5/16	3/8	(7/16)	1/2	5/8	(3/4)
A	max	0.180	0.212	0.230	0.286	0.341	0.412	0.480	0.605	0.730
	min	0.172	0.202	0.220	0.275	0.329	0.400	0.467	0.590	0.715
B	max	0.176	0.207	0.225	0.280	0.335	0.406	0.473	0.598	0.723
	min	0.137	0.161	0.176	0.220	0.263	0.320	0.373	0.472	0.572
c	min	0.380	0.440	0.500	0.620	0.750	0.880	1.000	1.250	1.500
D	min	0.090	0.100	0.110	0.140	0.160	0.200	0.230	0.300	0.360