




Forms allowed

Screw Thread d		0#	1#	2#	3#	4#	5#	6#	8#	10#	12#	1/4	5/16	3/8
d		0.0600	0.0730	0.0860	0.0990	0.1120	0.1250	0.1380	0.1640	0.1900	0.2160	0.2500	0.3120	0.3750
PP	UNC	80	64	56	48	40	40	32	32	24	24	20	18	16
s	max	0.156	0.156	0.188	0.188	0.250	0.312	0.312	0.344	0.375	0.438	0.438	0.562	0.625
	min	0.15	0.15	0.18	0.18	0.241	0.302	0.302	0.332	0.362	0.423	0.423	0.545	0.607
k	max	0.05	0.05	0.066	0.066	0.098	0.114	0.114	0.13	0.13	0.161	0.193	0.225	0.257
	min	0.043	0.043	0.057	0.057	0.087	0.102	0.102	0.117	0.117	0.148	0.178	0.208	0.239